

# LIQUIDITY SERVICES HMMWV Condition Sheet

Date:

This document is provided without warranty and is not a guarantee of condition

Lot Number: 13		Manufacturer: AM General	
Serial Number: 169012		Registration number: N64PTN	
Year: 11/95		Model: M1025A2	
Engine: GM 8 cylinder 6.5L diesel		Fuel: Diesel; 27 gallon fuel tank	
Turbo:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Equipped with AC	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Engine condition:		Odometer Reading: 9702.9	
Color: SAND		Date last overhauled: 3/08	
Transmission: Automatic 4L80E		Transfer case: NP 242	
Equipped with Front Brush Guard	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Front Winch Mile Marker Hydraulic:	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
Seats	Present	Condition Score	Present
Front	Driver: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	1 2 3 4 5	Passenger: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
Rear	Driver: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	1 2 3 4 5	Passenger: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>

Additional notes on interior condition:

Doors: Fabric / Steel	Present	Condition Score	Present	Condition Score
Front	Driver: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	1 2 3 4 5	Passenger: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	1 2 3 4 5
Rear	Driver: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	1 2 3 4 5	Passenger: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	1 2 3 4 5

Brakes	Condition Score	Condition Score
Front: Disk	Driver: 1 2 3 4 5	Passenger: 1 2 3 4 5
Rear: Disk	Driver: 1 2 3 4 5	Passenger: 1 2 3 4 5

Wheels and tires	Manufacturer	Size	Tread 1/32"	Condition Notes
Front - Driver	BF Goodrich	37x12.5 R16.5 LT	14/32	Good
Front - Passenger	↓	↓	12/32	↓
Rear - Driver	↓	↓	13/32	↓
Rear - Passenger	↓	↓	13/32	↓

Exterior - Other	Present	Condition Score	Condition Score
Glass	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	1 2 3 4 5	Paint 1 2 3 4 5
Tailgate	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	1 2 3 4 5	Frame 1 2 3 4 5

Exterior Lights	Present	Functions	Present	Functions
Front left	Head light Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes No Turn signal	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
Front right	Head light Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes No Turn signal	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
Left rear	Tail light Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes No Turn signal	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
Right rear	Tail light Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes No Turn signal	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>

Vehicle Function Test - Flat Ground at Low Speed without Load

Starts and Runs	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Brakes stop vehicle	Yes <input type="checkbox"/> No <input type="checkbox"/>
Drives forwards	Yes <input type="checkbox"/> No <input type="checkbox"/>	Steering operational	Yes <input type="checkbox"/> No <input type="checkbox"/>
Drives in Reverse	Yes <input type="checkbox"/> No <input type="checkbox"/>	Gauges Operational	Yes <input type="checkbox"/> No <input type="checkbox"/>
4 wheel drive engages	Yes <input type="checkbox"/> No <input type="checkbox"/>	Fluid Leaks Visible	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>

Fluid leaks: type and location:

Exterior dimensions: Length 191", Width 86", Height 66", ship weight 6,780 lbs

Additional Notes  
 Equipped with Rod Hall suspension on front and rear. Roof has cut out for a gun mount.  
 Will NOT START